

## Tsubaki Advantage Success Story

|                          |   |
|--------------------------|---|
| <b>Application No.:</b>  | <a href="#">5993</a>  |
| <b>Industry:</b>         | Forestry - Sawmill  |
| <b>Application Name:</b> | Chip Conveyor Chain 550-551   |
| <b>Issue:</b>            | Attachment weld cracking  |
| <b>Tsubaki Solution:</b> | Customer was experiencing attachment failure due to poor weld quality on the original chain. A22 attachments are welded to the middle of the sidebar and would break off during operation. Tsubaki's licensed welders applied proper pre-heat, welding, and cool-down processes to ensure there would be no attachment failures in the field. |
| <b>Cost Saving:</b>      | \$9,950.74  |
| <b>Item No.:</b>         | WH124IBR/A226L  |
| <b>Product Type:</b>     | Welded Steel Chain  |

Images:

