


Tsubaki Advantage Success Story

Application No.:	# 9542
Industry:	Agriculture
Application Name:	Seed Bucket Elevator-Light duty
Issue:	Current OEM chain has worn out, lasted 5 years. Challenge is lack of staff to do reliability maintenance to chains. They need to lubricate, but only gets to site 1-2 times/ yr and usually have to fix something.
Tsubaki Solution:	Offered Tsubaki Premium chain in Lambda. Maint/lube free. Was more money than the OEM, but huge cost savings potential. Just in year one, with no maint needed. Would like to get 10years out of chain
Cost Saving:	Maint 2hrs x \$50/hr- \$100 + \$1000 downtime= \$1100.00/ mo maint cost to lubricate, maintain. ROI 6 months.
Product Type:	VIP ROLLER CHAIN
Images:	 <p>The image block contains three visual elements: a photograph of the physical chain installed in a wooden seed bucket elevator; a 3D CAD model of the entire elevator assembly showing the chain path around three sprockets; and a technical drawing of the chain with dimensions such as 0.875, 0.750, 1.125, 0.906, 1.000, 2.000, 1.000, and 1.500. The drawing also labels '4 PITCHES', 'TYPICAL REPEATING SECTION', 'TOTAL 80 PITCHES', and 'CONN LINK'.</p> <p style="text-align: center; font-size: small;">MATCHED AND TAGGED WITH C2060HLATT4L-RH-MT (MIRRORED - ATTACHMENTS ON INSIDE)</p>