

**Tsubaki Advantage Success Stories**

<b>Application No.</b>	7225
<b>Industry</b>	FOOD-Food Processing
<b>Application Name</b>	Blancher - Plant One
<b>Issue</b>	Blancher 6-inch stainless steel chain was previously supplied by the OEM (Aeroglide supplied by Renold). The OEM chain had a lot of issues with bushings cracking and chain stretching, causing stainless pans to separate.
<b>Tsubaki Solution</b>	Tsubaki replacement chain (6" PSSHDA11Blancher) uses a different bushing material and heat treatment process to eliminate the problems above.
<b>Cost Savings</b>	91,204.15
<b>Product Type</b>	Engineered Class Chain-EC Roller Conveyor Chain
<b>Images</b>	No Images