

SUCCESS STORY

Chain Issues in a High-speed Environment

\$20,100

IN COST SAVINGS



PROBLEM

With the drives in a client's application operating in a high-speed environment, there was inadequate lubrication of the chain due to the excessive speed causing accelerated elongation. This led to the competitor's chain that was initially installed being replaced every two months.



SOLUTION

After switching the application to **Tsubaki's Speed Master chain** with hard-chromed plated pins, the customer experienced 14 months of life out of its chain without unnecessary downtime or maintenance.

The pin's hard surface prolonged the elongation period, making critical drives last longer with cost savings of over \$20,000.