

Tsubaki Advantage Success Stories

Application No.	3824
Industry	AUTOMOTIVE-Tier One
Application Name	Hi Feature (Oven)
Issue	Chain wear. OEM supplied
Tsubaki Solution	Tsubaki was called in to identify, inspect and supply a quote on the high feature chain at a food plant. This chain has special notched side plates and issued to transfer automotive crank shafts into an oven for hardening. The chain was originally supplied by the oem. We identified the chain and measured it for elongation. The chain was stretched causing issues with sprocket engagement. This is a special combination stainless steels due to the high temperatures. We supplied a quote matching the OEM spec. Our delivery was better and with the issues they were having Tsubaki received the order. We monitored the chain using Tsubaki Advantage and contacted the customer when it was time to replace again. This proactive approach prevented the customer from ordering from the OEM again as well as helping them be prepared and avoid a breakdown issue as before.
Cost Savings	49,907
Product Type	Engineered Class Chain-EC Roller Conveyor Chain
Images	