

Tsubaki Advantage Success Stories

Application No.	7410
Industry	FOOD-Food Processing
Application Name	Tabletop Boxing Line
Issue	This machine was only 6 months old when Tsubaki was called in. The customer said the chain had elongated at an accelerated rate and was causing the 3 strands to lose timing. When we got on site, we discovered it was a tabletop chain with carbon steel base chain and plastic tops that clicked onto the chain.
Tsubaki Solution	Tsubaki manufactured custom chain that incorporated special extended pins to utilize the original plastic tops that were still in good condition. We also added both our Lambda lube free and Neptune corrosion resistant coating so that we could extend the life of the chain and prevent corrosion that they have had issues with in the past. This application was timed so we added pre-stretching, matching and tagging to the chain prior to shipping so it didn't have a break in period and all the 3 strands lined up as closely as possible.
Cost Savings	0
Product Type	Conveyor Chain-Attachment Chain
Images	No Images