

## Tsubaki Advantage Success Stories

<b>Application No.</b>	5718
<b>Industry</b>	FORESTRY-Forestry
<b>Application Name</b>	Ashes conveyor 424
<b>Issue</b>	Customer using a S698 competition Drop forged chain. Link are exploding after less than a month of usage causing a lot of down time every day. Being a power plant, this translate to very expensive repair.
<b>Tsubaki Solution</b>	<p>Tsubaki DSM went on site with Tsubaki Technical service. After a meeting with the end user, engineering had a visit around the application. It's been decided with UST Engineering that the best solution would be to offer a triple zinc plated chain. This low-cost add-on would increase corrosion resistance and reduce bearing pressure.</p> <p>After one full year, the Tsubaki chain is still running w/o any maintenance required resulting to a more efficient production and a significant cost saving that still grow.</p>
<b>Cost Savings</b>	107,396.93
<b>Product Type</b>	EC Steel Barloop Chain
<b>Images</b>	